


# ALUMINIUM HIGH PRESSURE DIE CASTING DEFECTS ANALYSIS CHART

DEFECT TYPE



**SHOT FILL**  
SHOT FILLING DEFECTS ARE CAUSED BY IMPROPERLY PACKED SAND OR IMPROPERLY PLACED PARTS IN THE MOLD.

**COLD SHUT**  
COLD SHUTS ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**SCALING**  
SCALING IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**BURSTERS**  
BURSTERS ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**FLASH**  
FLASH IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**COLDFLAKES**  
COLDFLAKES ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**SHOT LUBE STAIN**  
SHOT LUBE STAIN IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**AIR POROSITY**  
AIR POROSITY IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**DRAG MARKS**  
DRAG MARKS ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**HOT TEAR CRACKING**  
HOT TEAR CRACKING IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**HOT SHRINKS**  
HOT SHRINKS ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**SINK**  
SINK IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**EXPLODED METAL**  
EXPLODED METAL IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**WARPAGE**  
WARPAGE IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**SOLDERING**  
SOLDERING IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**SHRINKAGE POROSITY**  
SHRINKAGE POROSITY IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**HEAT CHECKING**  
HEAT CHECKING IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**SPARKS**  
SPARKS ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**BREAK OUT**  
BREAK OUT IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.


**DISCOLOURED SURFACE**  
DISCOLOURED SURFACE IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**EROSION/COMPACTUM**  
EROSION/COMPACTUM IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**CRACKED CASTING**  
CRACKED CASTING IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**ELECTRON DAMAGE**  
ELECTRON DAMAGE IS CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.

**INCLUSIONS**  
INCLUSIONS ARE CAUSED BY IMPROPERLY HEATED METAL OR IMPROPERLY TIMED POURING.



## POSSIBLE CAUSES

1. Metal surface too low
2. Metal surface too high
3. Charge overfilled too low
4. Charge overfilled too high
5. Charge overfilled too early
6. Charge overfilled too late
7. Metal surface too low
8. Metal surface too high
9. Metal surface too early
10. Metal surface too late
11. Metal surface too low
12. Metal surface too high
13. Metal surface too early
14. Metal surface too late
15. Metal surface too low
16. Metal surface too high
17. Metal surface too early
18. Metal surface too late
19. Metal surface too low
20. Metal surface too high
21. Metal surface too early
22. Metal surface too late
23. Metal surface too low
24. Metal surface too high
25. Metal surface too early
26. Metal surface too late
27. Metal surface too low
28. Metal surface too high
29. Metal surface too early
30. Metal surface too late
31. Metal surface too low
32. Metal surface too high
33. Metal surface too early
34. Metal surface too late
35. Metal surface too low
36. Metal surface too high
37. Metal surface too early
38. Metal surface too late
39. Metal surface too low
40. Metal surface too high
41. Metal surface too early
42. Metal surface too late
43. Metal surface too low
44. Metal surface too high
45. Metal surface too early
46. Metal surface too late
47. Metal surface too low

**LEGEND FOR COLOR**

- Red circle = most likely cause
- Yellow circle = possible cause
- Green circle = least likely cause